Date	Service/Repair Performed	Performed By	Parts Used	Run Hours
11/23/20	Replaced inner dome membrane			
11/23/20	Tank level radar sensor installation	JCR		
12/10/21	Green Arrow - Installed network cards for tank radar sensor. Corrected ip address issues with remote access.	Green Arrow - Chris Y.		
12/22/21	Jetted out DP to Lagoon discharge pipe	JCR/SE/ Roto- Rooter		
05/18/21	Replaced A-003 mixer seal cartridge	JCR/JK/SE	See master parts list	
08/24/21	Tannk cleanout complete	MPW		
08/25/21	Replaced A-005 mixer seal cartridge	JCR	See master parts list	51251:59:49
08/31/21	Replaced A-003 mixer seal cartridge	JCR	See master parts list	48276:35:50
00/21/21	Pressurized and greased mixer A-002	JCR	50/50 glycol, grease	53634:07:30
08/31/21	Pressurized and greased mixer A-004			53686:52:52
09/20/21	Added Glycol to gas sensing line	SE	2.5 50/50 glycol	
11/02/21	Emptied and Refilled over/under valve with 50/50 glycol	SE		
***************************************				

Reason for Service					
suspected puncture/tear					
upgrade - ability to sense actual material level					
Tank sensor upgrades, ip address issues					
clogged					
Mixer seal failed - not holding pressure.					
Routine maintenance					
Mixer seal failed - not holding pressure.					
Mixer seal failed, glycol leaking from weep hole					
PM					
PM					
Preventative Maintenance					
Preventative Maintenance					

